GOODWE

V1.1-2026-09-21

HCA Series AC Charger

(GW7K-HCA-G30 | GW11K-HCA-G30|GW22K-HCA-G30|GW7K-HCA-UK-G30 | GW11K-HCA-UK-G30 | GW22K-HCA-UK-G30)

Quick Installation Guide
快速安装指导

Copyright © GoodWe Technologies Co., Ltd. 2026. All rights reserved.
版权所有©固德威技术股份有限公司 2026。保留所有权利。

EN-English

- The information in this quick installation guide is subject to change due to product updates or other reasons. This guide cannot replace the product labels or the safety precautions in the user manual unless otherwise specified. All descriptions here are for guidance only.
- All operations should be performed by trained and knowledgeable technicians who are familiar with local standards and safety regulations.
- Strictly follow the installation, operation, and configuration instructions in this guide and user manual. The manufacturer shall not be liable for equipment damage or personal injury if you do not follow the instructions.

ZH-中文

- 因产品版本升级或其他原因，本文档内容会不定期进行更新。如无特殊约定，本文档不可取代产品标签或用户手册。本文档中的所有描述仅作为使用指导。
- 设备所有操作必须由专业、合格的电气技术人员进行，技术人员需熟知项目所在地相关标准及安全规范。
- 未按照本文档或对应用户手册要求安装、使用、配置设备造成的设备损坏或人员伤害，不在设备厂商责任范围之内。

Official Website　官方网站　More Info


340-01511-01

GoodWe Technologies Co., Ltd.
No. 90 Zijin Rd., New District,
Suzhou, 215011, China
www.goodwe.com
service@goodwe.com


固德威技术股份有限公司
中国 苏州 高新区紫金路90号
T: 400-998-1212
www.goodwe.com
service@goodwe.com

Procedure


1 EN Installation　ZH 安装




Ⓐ :Tethered/枪线一体
Ⓑ :Untethered/枪线分离




Remove charger wall mounting plate
拆除充电桩背挂板




Remove front cover of RCBO distribution box
拆除RCBO配电盒前盖板



Wall-Mounting/挂墙安装




Post Mounting/柱式安装



Procedure


2 EN Electrical Connection ZH 电气连接

AC (AC INPUT)




HCA30ELC0001

RCBO




HCA30ELC0002




HCA30ELC0003

COM (RS485)




HCA30ELC0006

COM (RJ45)




HCA30ELC0004




HCA30ELC0005

MID Meter




HCA30ELC0007

SIM CARD



HCA30INT0005

3 EN Commissioning and Monitoring ZH 调测



HCA30PWR0001

SEMS+ App

or

SEMS+ WEB